

2022 MONTHLY ROADWORK AND REQUESTS REPORT

Report Compiled by Cathy Glatthar from Monthly Operations Manager's Reports

ROADWORK: G=Grading (Incl Watering, Compacting, Escapes), CE=Class E, D=Ditching, CC=Culvert Cleaning, CI=Culvert Install, W=Watering, AM=Asphalt Maint (Patching, Crack Sealing, Striping, Shouldering, Sweeping, etc.), SR=Snow Removal, MC=Mag-chloride, CS=Chip Seal, EP=Edge Paving, ER=Emergency Repairs, DR=Debris Removal, DG=DG Added, R=Request Received

			2022 Operations Manager's Report Date											
P=Paved UP=Unpaved	Road Segment	Miles	01/16	02/13	03/13	04/17	05/15	06/12	07/17	08/14	09/11	10/16	11/13	12/11
UP	Amy (N)	0.1												
UP	Amy (Whiskey Springs - James Ranch)	1.57				R			CE prtl	G				
P	Amy (James Ranch - Ironwood)	0.88	CC(1)					AM	CS					
UP	Amy (Ironwood - Wilcox Ranch)	0.4	CC(3)		R prtl		G prtl			RGMC prtl	MC prtl			
UP	Amy (S) (Wilcox Ranch - End)	1.4	CC(1)	D				G						
UP	Anniversary	0.5				G						R/G		
P	Axe Handle (Pyramid - Curnow Canyon)	3	SRx2						CS prtl	CC(1)				
P	Bacon Rind (N: Axe Handle - End of Surfacing)	0.5												
UP	Bacon Rind (N: End of Surfacing - End)	1.2												
UP	Bacon Rind (S: Axe Handle to Sky Canyon)	1.25	SR			G				R		R	R/G/CE	
UP	Bacon Rind (S: Sky Canyon - End/Sage Cyn)	0.25	SR			G							G	
UP	Big Dog (Prairie - Turn/4700 Big Dog)	0.6							G					
UP	Bootstrap	0.5												
UP	Broken Spur (N)	0.2												
UP	Broken Spur (S: Whiskey - Tumbleweed)	0.38	G		R	G		R	R/G			R/G	R	
UP	Broken Spur (S: Tumbleweed - Morgan Ranch)	1.12			R	G		R	R/G prtl			R/G prtl	R	
P	Broken Spur (S: Morgan Ranch - Sharrock)	0.9			R	AM						AM	EP/CS	
UP	Chantry Flats	1.1		D				G	G			G/D/DG		
UP	Chieftan (Pasture View - Vista Trail)	0.8											R	
UP	Crazy Horse (Wilcox - Yellow Tail)	0.73	CC(1)	D				G						
UP	Crazy Horse (Yellow Tail - End)	0.37		D										
UP	Crossover (N)	0.2												
UP	Crossover (Wild Horse - Twin Springs)	0.6									R		R/G	
UP	Curnow Cyn (Axe Handle - Quonset)	0.9	R/SRx3					G				R	G	
UP	Curnow Cyn (Quonset - Top of Hill 455 CCRd)	0.9	R/SRx3					G				R	G	
UP	Curnow Cyn (Top of Hill - Stop/190 CCRd)	0.8	R/SRx3					G					G	
UP	Easy Jet (Range Land S - End)	0.4												
UP	Flagstone	0.2												
UP	Grass Valley (W) (Pyramid - Flying Eagle Air)	1.6	D			R/G		R	G		G prtl			
UP	Grass Valley (W) (Flying Eagle Air - End)	2.25				R/G			G prtl		G prtl			
UP	Grass Valley (Pyramid - Wayside)	2.6					G prtl							
UP	Grass Valley (Wayside - Whiskey)	0.5					G		G				R/G	

2022 MONTHLY ROADWORK AND REQUESTS REPORT

2022 Operations Manager's Report Date														
P=Paved UP=Unpaved	Road Segment	Miles	01/16	02/13	03/13	04/17	05/15	06/12	07/17	08/14	09/11	10/16	11/13	12/11
UP	Grass Valley (S) (Whiskey - Turf Farm)	0.8												
UP	Grass Valley (Sharrock N - Turn Around)	0.8												
UP	Grey Van (Range Land S - End)	1.2	G			R	G			G			G	
UP	Hay Canyon	0.3												
UP	Hockberry	1	CC(1)				G						G	
P	Ironwood (Pyramid - Ironwood Crossover)	0.7	AM			AM								
P	Ironwood (Ironwood Crossover - Pit)	2	AM			AM								
P	Ironwood (Pit - Amy)	2.2	D/AM	CC(1)	R	AM		AM	AM/CS	AM				
UP	Ironwood (Crossover/Little)	1						G						
UP	Jackrabbit (S)	0.5							G					
UP	Jackrabbit (N)	0.5							G					
UP	Lost Spring	1							G					
UP	Mid	0.3		D							R			
UP	Morning Dove	0.2												
UP	Pasture View (Whiskey - Sharrock)	1.5										G		
UP	Pasture View (Sharrock - South End)	0.5										G		
UP	Pasture View (N)	0.8				R/G						G		
UP	Peak (E - W)	0.7				G			G			G		
UP	Peak (N - S)	1.7							G		Sign			
UP	Pioche	0.2												
UP	Piute Creek (Whiskey - Turn)	0.5										R		
UP	Piute Creek (Turn - Stop/2155 PCRd)	1.2	SR											
UP	Pony Springs	0.8												
UP	Prairie (Winnemucca - Big Dog)	0.45				G/CE/MC								
UP	Prairie (Big Dog - Jackrabbit)	0.55				G/CE/MC								
UP	Quaking Aspen (Wilcox - O'Hara)	2		D		R	G/D	R	R	G	CE/ER/MC	MC prtl		
UP	Quakng Aspen (O'Hara - Microwave)	1.4	R					R	R					
UP	Quaking Aspen (Microwave - Rossow)	1						R						
UP	Quaking Aspen (Rossow - Mtn Aspen)	0.9												
UP	Range Land (Pyramid - Cattle Guard)	0.03					Ctl Grd			G				
P	Range Land (Cattle Guard - Easy Jet)	0.37		CE	MC	MC				MC				
P	Range Land (Easy Jet - Grey Van)	0.5		CE	MC	MC	AM			MC				
UP	Range Land (Grey Van - Rebel Cause)	0.5	G	CE	MC	MC				G/MC			G	
UP	Range Land (Rebel Cause - Peak)	0.5	G	CE	MC	MC				G/MC				
UP	Range Land (Peak - Winnemucca)	1	G	G		G		G					G	



## PVGID OPERATIONS MANAGER'S REPORT

Report Period 12/13/2021 to 1/16/2022

ATTACHMENT: 01/20/2022 Meeting Agenda Item 6.b.

### ROADS GRADED AND/OR COMPACTED:

1. Grey Van
2. Rebel Cause
3. Range Land: Grey Van to Peak
4. Range Land: Peak to Winnemucca Ranch
5. Broken Spur: Whiskey Springs to Tumbleweed
6. Wilcox Ranch: Crazy Horse to Quaking Aspen (Spot Grading)

### OTHER ROAD WORK:

1. Axe Handle: Plow snow x 2
2. Curnow Cyn: Plow snow x 3
3. Bacon Rind S: Plow snow
4. Whiskey Springs: Wild Horse to top - plow snow
5. Piute Creek: Upper - plow snow
6. Inspect culverts on East side of valley
7. Ironwood: Ponding water on road near pit. Deepen ditch to get water to flow
8. Grass Valley W: Ponding water on roadway. Deepen ditch to get water to flow
9. Ironwood: Re-stripe
10. Ironwood Pit: Someone pulled the gate open braking the chain and lock and ripping out a post - Reset
11. Crazy Horse: Clean culvert
12. Amy: Clean 5 culverts
13. Hockberry: Clean culvert

### OTHER:

1. Office work
2. Road committee meetings
3. GID Meeting
4. Post Agenda
5. Road Surveys
6. Town for parts
7. Misc. Yard work
8. Employees Off for Christmas and New Year's Holidays
9. Employees - 63.5 hours Time Off Taken

### EQUIPMENT:

1. 770 & 670 Graders: Install & pull chains
2. 05 Compactor: Les Schwab Drained Mag Chloride from old tires, Installed new tires and refilled with Mag. Fuel line leaking from tank to pump, and return line leaking back to tank R&R. Batteries bad. Replaced with deep cycle batteries
3. 03 580sm Backhoe: Les Schwab R&R new rear tires
4. 93 Broce Kick broom: Les Schwab Swapped tires from pull Kick broom
5. 02 Peterbilt: Les Schwab patched left front drive tire
6. 04 F450: Les Schwab Patched rear outer tire. Plow stopped working, has electrical problem - Diagnosing
7. 80 Weld truck: Transmission service
8. 88 6.2 Pickup Truck: Transmission would not engage in drive, did trans service, still would not drive. Trans bad - take to shop to have new trans installed.
9. 97 Vactor: Both suction hoses old and tearing - R&R. Have to prep for freezing temperatures at end of the day.

PVGID OPERATIONS MANAGER'S REPORT  
Report Period 1/17/2022 to 2/13/2022  
ATTACHMENT: 2/17/2022 Meeting Agenda Item 5.b.

ROADS GRADED AND/OR COMPACTED:

1. Lost Spring: Roads are still too frozen! Dirt just wants to chunk and then doesn't want to spread evenly.
2. Range Land: Peak to Winnemucca - Smooth for trucking.

OTHER ROAD WORK:

1. Ironwood: Clean culvert near #460
2. Amy South: Ditch and escape work
3. Crazy Horse: Ditch and escape work
4. Yellow Tail: Ditch and escape work
5. Chantry Flats: Ditch and escape work
6. Wilcox Ranch: Quaking Aspen to Mid - Ditch and escape work
7. Mid Rd: Ditch and escape work
8. Quaking Aspen: Wilcox to O'Hara - Ditch and escape work
9. Range Land: Do some prep work for project, Pull ditches. North side still wet, South side still frozen. Spread 4614.92 tons of Class E from cattle guard to Peak

OTHER:

1. Office work
2. Road committee meetings
3. GID Meeting
4. Post Agenda
5. Road Surveys
6. Town for parts
7. Misc. Yard work
8. Cattle Guards for Range Land Road - Rebuild
9. Bar None Auction: Preview Equipment. Purchase 772D Motor Grader.

EQUIPMENT:

1. 97 Vactor: Rodder hose broke. Took hose to town; purchased and installed new coupler.

## PVGID OPERATIONS MANAGER'S REPORT

Report Period 2/14/2022 to 3/13/2022

ATTACHMENT: 3/17/2022 Meeting Agenda Item 5.b.

### ROADS GRADED AND/OR COMPACTED:

1. Wilcox Ranch: Spread 3390.62 tons of Class E from near 5255 Wilcox Ranch to near 2850 Wilcox Ranch - 2.7 miles

### OTHER ROAD WORK:

1. Range Land: Spray 2,000 gallons of mag-chloride on new Class E

### OTHER:

1. Office work
2. Road committee meetings
3. GID Meeting
4. Post Agenda
5. Road Surveys
6. Town for parts
7. Misc. Yard work
8. Cattle Guards for Range Land: Prep and Prime
9. Ironwood well: Replace gate-valve seal

### EQUIPMENT:

1. '91 670 Grader: Change oil & filter, fuel filter, air filter, lube. Prep grader to put up for sale. Removed all GID equipment.
2. '03 770 Grader: Change oil & filter, air filter, lube. Had six new tires installed.
3. '01 F450: No start when cold. Block heater inoperable - had replaced, had glow plugs and relay checked, they were good. Changed oil & filter, lube. Changed fluid in front and rear differentials.
4. '05 772 Grader: Inspect machine completely as new to fleet. Change oil, lube, install new block heater, missing ladder on side of cab - install new, redirect auxiliary hydraulic hoses and remove auxiliary hydraulic levers (Not in use), install company radio and antenna, install SK's CB radio for Class E delivery, install warning light, change front head lights back over from high snow lights back to original lower position, right upper door hold open latch inoperable - repair. Had to build and weld a brace to protect accumulator on side of frame. Had Les Schwab Install six new tires.
5. '02 Pete: Change oil & filter, lube.
6. '05 IR Compactor: Hydraulic hose failed - remove, take to town to have one made - install new hose.

## PVGID OPERATIONS MANAGER'S REPORT

Report Period 3/14/2022 to 4/17/2022

ATTACHMENT: 4/21/2022 Meeting Agenda Item 5.b.

### ROADS GRADED AND/OR COMPACTED:

1. Bacon Rind S
2. Wild Horse: Crossover to Silver Horse
3. Silver Horse
4. Range Land: Peak to Winnemucca
5. Roadrunner
6. Two Forty
7. Prairie
8. Anniversary
9. Peak E-W
10. Pasture View N
11. Wild Horse N: Whiskey Springs to Flagstone
12. Grass Valley W: Pyramid to 7005 Grass Valley
13. Prairie: Spread 1738.7 tons of Class E
14. Broken Spur: Whiskey Springs to Morgan Ranch
15. Sage Flat

### OTHER ROAD WORK:

1. Wilcox Ranch: Spray mag-chloride near 5255 Wilcox to near 2850 Wilcox - 2.7 miles
2. Range Land: Spray mag-chloride on new Class E
3. Grass Valley W: Near 7600, repair hole in culvert and cover with base
4. Ironwood: Pothole patch .45 tons
5. Right Hand Cyn: Pothole patch 2.65 tons
6. Prairie: Spray mag-chloride on new Class E
7. Broken Spur: Sweep and pothole patch .50 tons

### OTHER:

1. Office work
2. GID Meeting
3. Post Agenda
4. Road Surveys
5. Town for parts
6. Misc. Yard work

### EQUIPMENT:

1. 91 670B Grader: Sold
2. 6 old grader tires: Sold
3. Chip spreader parts: Sold
4. 88 Patch Truck: Injector pump leaking fuel; remove, take to town for rebuild; install. Also replace fuel lines.
5. 01 Peterbilt: Lube
6. Zieman transport trailer: Had to replace all the boards on the back half of the trailer
7. 05 Int'l Water Truck: Weld tank again
8. 05 IR Compactor: Repair upper radiator hose; lube

## PVGID OPERATIONS MANAGER'S REPORT

Report Period 4/18/2022 to 5/15/2022

ATTACHMENT: 5/19/2022 Meeting Agenda Item 6.b.

### ROADS GRADED AND/OR COMPACTED:

1. Grey Van
2. Rebel Cause
3. Sharrock: Amy to Wild Horse
4. Hockberry
5. Quaking Aspen: Wilcox Ranch to O'Hara, Also clean up Ditches
6. Grass Valley: Whiskey Springs to near 5915 Grass Valley
7. Wayside Rd: Grass Valley to near 5105 Wayside
8. Twin Springs: Crossover to Cul-de-sac
9. Amy Short: Ironwood intersection and Wilcox Ranch intersection
10. Wilcox Ranch: Goodher to Mid and spot grade other areas

### OTHER ROAD WORK:

1. Ironwood, Amy, Axe Handle: Measure road areas for patch, then patch roads before chip seal
2. Right Hand Cyn: Whiskey Springs to end of pavement, sweep with kick broom, clean up drainage with grader, prep for patching and sealing
3. Range Land - Easy Jet to Grey Van: Pull shoulder backing to edge of road on North side (Blow sand - not good for backing material)
4. Range Land: Remove old cattle guard and replace, haul old cattle guard back to yard

### OTHER:

1. Office work
2. Attend meetings
3. Post Agenda
4. Road Surveys
5. Town for parts
6. Misc. Yard work
7. Meetings with Teichert
8. Cattle Guard: Paint

### EQUIPMENT:

1. 2000 Pete: Right rear outer tire had sidewall bubble, R&R with spare tire
2. 88 Int'l patch truck: Prep for edge paving, did some more fabrication
3. 05 Int'l water truck: Truck keeps dying, check engine light on. American Truck came out, used scanner to find issues, they R&R the Cam & Crank sensors, plastic surge tank radiator cap loose, new tank costs \$700, repaired with JB Weld and repair is holding
4. 95 Pete water truck: Weld water tank (had lots of holes)
5. IR Compactor: R&R hydraulic filters



## PVGID OPERATIONS MANAGER'S REPORT

Report Period 5/16/2022 to 6/12/2022

ATTACHMENT: 6/16/2022 Meeting Agenda Item 5.b.

### ROADS GRADED AND/OR COMPACTED:

1. Crazy Horse: Wilcox Ranch to Hay Cyn
2. Yellow Tail: Pioche to End
3. Chantry Flats
4. Curnow Canyon: Axe Handle to End of Maintenance
5. Space Test
6. Little Ironwood
7. Right Hand Canyon: End of pavement to near 3655 RHC
8. Amy South: Wilcox Ranch to Cambrai Lane
9. Range Land: Peak to Winnemucca

### OTHER ROAD WORK:

1. Ironwood: Patch 14 tons cold mix from end of last year's chip seal to Amy in preparation for chip seal project
2. Amy: Transport kick broom and sweep in preparation for patching
3. Amy: Patch 4 tons cold mix from Ironwood to Sharrock in preparation for chip seal project
4. Right Hand Canyon: Patch 1.5 tons cold mix from end of pavement back to Whiskey Springs

### OTHER:

1. Office work
2. Attend Meeting
3. Post Agenda
4. Road Surveys
5. Town for parts
6. Misc. Yard work

### EQUIPMENT:

1. '88 Dump Truck: Transmission failed, take back to transmission shop for warranty repair
2. '05 Compactor: Radiator leaking, remove and take back to A1 Radiator for warranty repair work, re-install
3. '05 International Water Truck: Had metal debris from tank stuck in pump impeller, also some metal went through pump and stuck in water pod, removed all necessary pipes and rebuilt pod, also replaced the pipe ring gaskets. Flat tire right rear outer R&R. Truck died again, called American Truck repair out, they cleared all trouble codes and truck started and is running at this time
4. '03 770 Grader: Cut crown out of cutting edges

PVGID OPERATIONS MANAGER'S REPORT  
Report Period 6/13/2022 to 7/17/2022  
ATTACHMENT: 7/21/2022 Meeting Agenda Item 5.b.

ROADS GRADED AND/OR COMPACTED:

1. Peak: N-S
2. Peak: E-W
3. Lost Spring
4. Two Forty
5. Sharrock: Amy to Wild Horse
6. Grass Valley West: Pyramid to ¼ mile from end
7. Big Dog
8. Jackrabbit: North
9. Jackrabbit: South
10. Broken Spur: Whiskey Springs to Allium Ct
11. Twin Springs: Crossover to Cul-de-sac
12. Chantry Flats
13. Grass Valley: Whiskey Springs to Wayside

OTHER ROAD WORK:

1. Ironwood: Patch with 7 tons cold mix, Place striping markers in prep for chip seal
2. Amy & Ironwood intersection: Blade patch 24 tons cold mix in prep for chip seal
3. Whiskey Springs: Re-paint white lines from Pyramid to just past Broken Spur
4. Pull down some Class E at yard and mix with water to use for spot patching on Class E roads
5. Amy: Whiskey Springs south - spread 48 yards Class E

OTHER:

1. Office work
2. Attend Meeting
3. Post Agenda
4. Road Surveys
5. Town for parts
6. Misc. Yard work
7. Monthly vehicle hours/mileage and well readings
8. Holiday
9. One employee out for medical leave

EQUIPMENT:

1. '03 770 Grader: Lube; R&R cutting edges; Remove one wheel off Final Pass (compactor wheels) due to bearing failure; Support frame weld cracked on Final Pass, re-weld; Spray dirt out of radiator as engine was getting hot; Replace glide shim on lower moldboard, bolts broke, had to drill and tap to reinstall
2. '02 Peterbilt Tractor: Take to Mustang, NV to check out belly pup for clearances. Later went back to pick up belly pup after purchased, and brought back to yard
3. '01 F450 Pickup: Take to McDiesel to have new engine installed
4. '05 Intl Water truck: R&R two more o-ring gaskets on water pipe plumbing; Air line to right air tank bad, repaired
5. '88 6.2 Mini-dump Pickup: Change oil and filter, and fuel filter
6. '98 Peterbilt water truck: Perform truck inspection
7. '05 IR Compactor: Bar for screen hold down broke, weld

## PVGID OPERATIONS MANAGER'S REPORT

Report Period 7/18/2022 to 8/14/2022

ATTACHMENT: 8/18/2022 Meeting Agenda Item 5.a.

### ROADS GRADED AND/OR COMPACTED:

1. Wilcox Ranch: Goodher to Mid
2. Amy: Whiskey Springs to James Ranch
3. Amy @ Ironwood intersection: 300 feet south
4. Amy @ Wilcox Ranch intersection: 300 feet before Wilcox Ranch and 300 feet after
5. Range Land: Pyramid Hwy to Cattle Guard
6. Range Land: Grey Van to Peak
7. Grey Van
8. Rebel Cause
9. Quaking Aspen: Prep for Class E trucks

### OTHER ROAD WORK:

1. Ironwood: Stripe new Chip seal
2. Right Hand Cyn: Flash Flood Event - Graded to make road drivable. Used Kickbroom to clean paved section
3. Whiskey Springs Upper: Flash Flood Event - Lots of debris, cleaned road using Kickbroom
4. Twin Springs: Flash Flood Event - Concrete spillway: Remove 10 yards of debris; Upper culvert filled with debris and washed out road, Used backhoe to clean and repair roadway, pulled 15 yards of debris from in front of culvert, used Vactor to clean 4 yards of debris out of 35' of culvert
5. Wilcox Ranch Hill: Applied Mag-Chloride
6. Amy: Whiskey Springs to James Ranch, Applied Mag-Chloride
7. Amy @ Ironwood intersection: 300 feet south. Applied Mag-Chloride
8. Amy @ Wilcox Ranch intersection - 300 feet before Wilcox Ranch and 300 feet after: Applied Mag-Chloride
9. Range Land: Cattle Guard to Peak, Applied Mag-Chloride
10. Wild Horse and Sharrock: Used Vactor to Clean 100' of culvert
11. Axe Handle Rd: Near 5605, Used Vactor to Clean 35' of culvert

### OTHER:

1. Office work
2. Attend Meeting
3. Post Agenda
4. Road Surveys
5. Town for parts
6. Misc. Yard work
7. Monthly Vehicle hours / mileage and well readings
8. One Employee on Vacation

### EQUIPMENT:

1. 05 Int Water Truck: Passenger side plastic door handle broke off, R&R; Tank leaking, welded
2. 93 Kick Broom: Service A/C
3. 05 772 Grader: Lube
4. 03 770 Grader: Lube
5. 02 Pete semi: Batteries bad, R&R
6. 98 Pete Water truck: R&R Tach and Speedometer; Short in wiring for back up alarm, Traced problem and repair; rear differential Indicator lite inop, R&R sending unit; Upper radiator hose had a split, R&R

## PVGID OPERATIONS MANAGER'S REPORT

Report Period 8/15/2022 to 9/11/2022

ATTACHMENT: 9/15/2022 Meeting Agenda Item 5.a.

### ROADS GRADED AND/OR COMPACTED:

1. Wilcox Ranch - Amy to just past Morning Dove: Spread 769.84 tons of Class E material
2. Quaking Aspen - First two miles: Spread 2,763.90 tons of Class E material
3. Quaking Aspen - Wilcox Ranch to O'Hara: Flash flood event washed out and deposited debris over roadway in multiple areas, had to import and spot spread an additional 741.22 tons of Class E material on the road to repair the damage
4. Wild Horse - Whiskey Springs to near 4400: Spread 2,532.24 tons of Class E material (Had to stop here because Teichert/Western Nevada Materials ran out of material)
5. Grass Valley West - Pyramid to near 7100 (Skipped Class E area)

### OTHER ROAD WORK:

1. Quaking Aspen - Wilcox Ranch to O'Hara: Flash flood event washed debris over roadway and filled in ditches and culverts in multiple areas. Clean ditches and debris from roadway using the Vactor (to locate culvert ends), Grader, and Backhoe. Brought in 10 yards of structural fill to place on downhill side of #1 culvert to cover exposed pipe and repair roadway
2. Wild Horse at Sharrock Intersection: Use Vactor to clean culvert
3. Wilcox Ranch - Across from 2855: Locate culvert end
4. Yellow Tail at the dip ¼ mile in from Crazy Horse: Locate and clean culvert end and culvert pipe, use backhoe to reinstall ditches to culvert, also clean debris off roadway
5. Quaking Aspen - Wilcox Ranch to O'Hara: Spray mag-chloride on road
6. Wild Horse - Whiskey Springs to near 4400: Spray mag-chloride on road
7. Amy Short at Intersection of Ironwood and intersection of Wilcox Ranch: Spray mag-chloride on road
8. Peak N-S: Yield sign ran over, reinstall sign

### OTHER:

1. Office work
2. Attend Meeting
3. Post Agenda
4. Road Surveys
5. Town for parts
6. Misc. Yard work
7. Monthly Vehicle hours / mileage and well readings

### EQUIPMENT:

1. '05 International Water Truck: Still had no start issue, had Silver State International come out to yard, found wire came off of IDM relay, reinstalled. Truck running at this time. Brake air valve leaking air, R&R.
2. '05 772 Grader: R&R Cutting Edges
3. Zieman Equipment trailer: Two tires bad, Les Schwab came out to replace

## PVGID OPERATIONS MANAGER'S REPORT

Report Period 9/12/2022 to 10/16/2022

ATTACHMENT: 10/20/2022 Meeting Agenda Item 6.a.

### ROADS GRADED AND/OR COMPACTED:

1. Wilcox Ranch: Amy to Crazy Horse
2. Broken Spur: Whiskey Springs to Allium Ct
3. Pasture View: N
4. Pasture View: Whiskey Springs to Sharrock
5. Pasture View: S
6. Sage Flat
7. Anniversary
8. Peak E-W
9. Right Hand Cyn: Beginning of Class E to 3300 RHC
10. Chantry Flats: Repair drainage and escapes, grade and spread 235 yards DG over exposed rock areas
11. Wrangler Rd: Repair drainage and escapes, grade and spread 161yards DG over exposed rock areas

### OTHER ROAD WORK:

1. Whiskey Springs at Pyramid: Stop sign hit and knocked down, Reinstall
2. Wilcox Ranch between Charlie's curve and Goodher: Haul shoulder backing to fill in areas where flash flooding washed away shoulders and used backhoe to fill
3. Quaking Aspen - Wilcox Ranch to O'Hara: Spot areas with Mag-chloride
4. Wilcox Ranch: Mag-chloride bridge and S-turn over large culvert
5. Right Hand Cyn - Wrangler to Raptor: Pull ditches and escapes
6. Right Hand Cyn: Sweep to prep for micro-paving; Used 7 tons of cold mix near end of pavement to finish the patching (that the contractor did not complete) in preparation for micro-surfacing
7. Sharrock - Amy to Broken Spur: Sweep in prep for edge paving and chip seal
8. Broken Spur - Sharrock to Morgan Ranch: Sweep in prep for edge paving and chip seal
9. Ironwood Pit: Push and screen material

### OTHER:

1. Office work
2. Attend Meeting
3. Post Agenda
4. Road Surveys
5. Town for parts
6. Misc. Yard work
7. Monthly Vehicle hours / mileage and well readings

### EQUIPMENT:

1. 98 Pete water truck: Prep for Auction and take to Gardnerville (Sold)
2. 05 Int. water truck: Engine has a miss, had Silver State Int. check with scanner. Conclusion, Scanner did not find anything, Mechanic said the engine is worn out. Check IPR valve, it was bad R&R. Pull valve cover & high pressure oil rail replaced O-rings and Jake brake valve. "Still not right". Had bad wiring at Headlamps and tail lights, Repaired.
3. 96 Pete Bobtail: Had Silver State Int change parameters in ECM to stop it from shutting off after 5 minutes at idle
4. 01 F450: Radiator upper hose outlet broke off, R&R Radiator and upper hose
5. 95 Pete water truck: Weld patches of sheet metal over holes in tank. New steer tires.
6. 93 Kick broom: Air box cover fell off ceiling, Reinstall
7. 89 Dozer: R&R batteries

## PVGID OPERATIONS MANAGER'S REPORT

Report Period 10/17/2022 to 11/13/2022

ATTACHMENT: 11/17/2022 Meeting Agenda Item 5.a.

### ROADS GRADED AND/OR COMPACTED:

1. Range Land: Grey Van to Rebel Cause
2. Range Land: Peak to Winnemucca Ranch
3. Roadrunner
4. Bacon Rind S: Axe Handle to Sky Canyon - Re-cover the Class E where native soil came through with 601.94 tons of Class E
5. Bacon Rind S: Sky Canyon to End of Maintenance
6. Wilcox Ranch: Amy to Big culvert
7. Sharrock: Amy to Wild Horse
8. Grass Valley (East): Whiskey Springs to Wayside
9. Wayside Rd: Grass Valley to Near 5105 Wayside
10. Curnow Canyon: Axe Handle to End of Maintenance (Used rented water truck)
11. Twin Springs: Spillway to Cul-de-sac
12. Grey Van
13. Rebel Cause
14. Two Forty
15. Hockberry
16. Wilcox Ranch: Crazy Horse to Quaking Aspen
17. Crossover

### OTHER ROAD WORK:

1. Twin Springs: Culvert full, clean out with Vactor
2. Wilcox Ranch: Culvert near 2855, Install 2 culvert markers
3. Ironwood: At Hockberry, Install culvert marker

### OTHER:

1. Office work
2. Attend Meeting
3. Post Agenda
4. Road and Sign Surveys
5. Town for parts
6. Misc. Yard work
7. Monthly Vehicle hours / mileage and well readings
8. Water truck rental
9. 2 Holidays

### EQUIPMENT:

1. 05 Int'l Water Truck: Checked exhaust manifold with heat gun, #1 cylinder not firing, R&R Injector and it was still not firing, but at this time we were able to use the water truck on low-elevation areas of the Valley, very low on power, looking for a used engine and water truck
2. Ironwood well: Generator would not start, Rodent had accessed start switch and chewed wires, Repaired
3. 02 Peterbilt Tractor: Suspension air bag leaking, R&R
4. 03 770 Grader: Cut crown out of cutting edges
5. 01 F450: Headlights faded, R&R headlights; New tires; Snow plow blade inoperable, Bad solenoid, R&R; Pump motor has lots of wear and should be replaced
6. 93 Kick Broom: Brushes worn, R&R
7. 95 Pete Water Truck: Not building air, Repair governor
8. 98 Belly Pup: Electrical 7-way plug bad, R&R